

100 Atlanta Technology Center, Suite 120, 1575 Northside Drive, NW, Atlanta, GA 30318 • (404) 352-4147

TECHNICAL ASSISTANCE TEAM FOR EMERGENCY RESPONSE REMOVAL AND PREVENTION EPA CONTRACT 68-01-7367

MEMORANDUM

TO:

Carol J. Walsh, OSC

FROM:

Freda D. Griffis FG

TAT, Region IV

Karen Jarrett-Gill KJ6

TAT, Region IV - Memphis Office

THRU:

James L. Templeton JUT

TATL, Region IV

David R. Daniel

QA/QC Officer

SUBJECT:

Report of Sampling Activities at the SAAD Site,

Nashville, Tennessee. TDD 04-8703-29-1064

TAT-04-F-00709

DATE:

15 April 1987

Introduction

This report has been prepared to satisfy the requirements of Technical Direction Document (TDD) 04-8703-29 issued to the Roy F. Weston Technical Assistance Team (TAT) by the U.S. Environmental Protection Agency (EPA). The field investigation was conducted between 16 and 27 March 1987 by the EPA Emergency Response Team (ERT) and the Environmental Emergency Response Unit (EERU) contractor. TAT members participating in this investigation were Freda Griffis and Karen Jarrett-Gill.

Sampling procedures used throughout this study were in accordance with the Environmental Services Division (ESD) Standard Operating Procedures (SOP) for field sampling and the sampling plan prepared by ERT and EERU personnel.

The overall scope of the project involved the collection of two composite tank samples and eleven water samples. A drilling contractor drilled 27 boreholes to determine extent of contamination in soil and groundwater underneath Saad Oil and surrounding areas (See Photographs, Attachment 1).

Roy F. Weston, Inc.

SPILL PREVENTION & EMERGENCY RESPONSE DIVISION

In Association with ICF Technology Inc., C.C. Johnson & Associates, Inc., Resource Applications, Inc., Geo/Resource Consultants, Inc., and Environmental Toxicology International, Inc.

All samples were shipped to an EERU contract lab under proper chain-of-custody for analysis for priority pollutants and PCBs.

Site Description

The Saad Oil Site is located at 3655 Trousdale Road in Nashville, Davidson County, Tennessee, 38204. A State Location Map is attached as Figure 1. A Site Location Map is attached as Figure 2.

The Saad Site consists of a concrete pad with a cinder block wall containing 14 tanks above ground and 1 underground tank (see Figure 3, Site Diagram). Approximately 20 feet outside the wall, on the treeline which separates the Saad property from the CSX Transportation Railyard, is a monitoring well. It is approximately 44 feet deep and is visibly contaminated with an oily substance. This well is reportedly located next to a sinkhole which was filled with debris and waste materials from the Saad Company's process. Adjacent to the Saad property exists a brick manufacturing facility.

John P. Saad & Sons, Inc. began operation of a waste oil pick-up service on Trousdale Road in 1970. Waste oil was brought to the site in tank trucks. In 1978, officials from the Tennessee Department of Water Quality Control discovered a discharge pond behind the facility which contained organic waste solvents. In 1982 the Water Resources Division of the Tennessee Department of Conservation was consulted about how the Saad waste may impact the Croft Spring nearby.

One reason this site is of continued interest to EPA is because the Croft estate, which is near the Saad property, is to be willed to the Cumberland Museum, which intends to convert the land into a children's park. The major surface water feature of the Croft estate is a spring near the homestead, which was once used as its water supply. This spring and the stream it forms would also be an important park feature, and there is public concern that children may become exposed to chemical contaminants present in the water. There are also several private wells downgradient of the site even though the entire area is on municipal water taken from the Cumberland River. These wells are mainly used for purposes other than drinking, e.g. irrigation of lawns and gardens.

Sampling Procedures

Sampling procedures used in this investigation were planned and executed by ERT and EERU. TAT provided technical support and monitoring during on-site activities.

Collection of samples and borehole drilling began on 16 March and all samples were collected by 27 March 1987. A Site Sketch Map, coded to show borehole locations, is attached as Figure 4.

- 1. Tank contents sampled--On 17 March, 5 tank samples were collected to be combined for one composite sample for priority pollutant and PCB analysis by an EERU contract lab. On 18 March, three additional tanks were sampled. All tank samples were composited for a total of two samples to be shipped out for analysis.
- 2. Borehole Drilling/Borehole Water Samples Collected-During the investigation, 27 borehole were drilled and water samples were collected from eleven of them for priority pollutant and PCB analysis by an EERU contract lab.
- 3. An Auto-Skimmer was set up in an existing monitoring well to determine whether a recoverable amount of oil existed in the ground water. It was determined by Paul McNally, EERU Geologist, that a recoverable amount of oil did not exist in the groundwater.

A Table of Witnesses/Participants is included as Attachment 2. All analytical results, maps, and discussion of results will be submitted in another report by ERT and EERU.

ATTACHMENT 1
Photographs




Figure 1 State Location Map

	ACTIVITY DESCRIPTION PA/SI	SITE The Saad Site
		TDD NO. 04-8610-23/04-8609-02
		DATE 10-30-86 BY -EG





Figure 2 Site Location Map

	ACTIVITY DESCRIPTION PA/SI	SITE The Saad Site
WESTER!		TDD NO. 04-8610-23 / 04-8609-02
		DATE 10-30-86 BY FG




•




BY KJG DATE 30Mar 87 SHEET _ w.o. no. (Not to Scale) TKD BY ____ DATE_ DEPT. OJECT <u>Saad Oil</u> 22 Fredtin Brick formal let Franklin 45 Brick Co 25 old gravel drive 18 lagoon 23 16 0000 0000 Bus Parking Lot Containment Saad Building (Klein and United) 11 Klein Kustom 26 Koachs dramage ditch gravel drive 27 screened holes air hammer holes United Coach Service Figure 4 Borehole Locations Company SAAD Site


POOR LEGIBILITY

PORTIONS OF THIS DOCUMENT MAY BE UNREADABLE, DUE TO THE QUALITY OF THE ORIGINAL


















5 5 0808
















6060 7 7

ATTACHMENT 2

Table of Witnesses

EPA Carol J. Walsh, OSC George Prince, ERT	404/347-2216 201/321-6649
TAT Freda D. Griffis Karen Jarrett-Gill	404/352-4147 901/398-6071
EERU Cindy Burchette, Biologist Paul Karmazinski, Geologist Paul McNally, Geologist	201/906-6823 201/906-6823 201/548-9660

GENERAL QUESTIONS TO RESIDENTS

- II. Are you using your well water for any purpose? If so what?
- i.e. A. drinking
 - B. bathing, showering or swimming
 - C. canning
 - D. livestock
 - E. crops
 - If answer is no STOP

If the answer is yes to A/B ask the following:

- 1. How often do you use the water for showering or swimming?
- 2. Have you noticed any unusual odor, color or taste with the water?
- 3. Give the ages of people who live in the house?
- 4. Have you or any member of the house noticed any unusual health problems?

If the answer is yes to item C ask the following:

- 1. How frequently do you use the water?
- 2. How do you use the water for canning?
- 3. Is the water boiled prior to use?

If the answer is yes to item D ask the following:

- 1. What kind of livestock drinks the water?
- Are the animals generally healthy.

If the answer is yes to item E ask the following:

- 1. What kind of crops do you grow?
- 2. Are they sold commercially or grown solely for your own use?

SPECIFIC QUSTION FOR PEOPLE WHO VOICED HEALTH COMPLAINTS IN 1979.

1. Have you had any recurrence of health problems you complained of in 1979 since you discontinued using the well water?

QUESTIONS TO STATE

I. Are any households or businesses in the contaminated or potential contaminated area of Silver Springs using well water? If so how many and how long?